



KALORAMA REC LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 KALORAMA RECREATION CENTER	5/26/2016	WS- 012666	Utility	1	In men's bathroom utility closet main line	WT-042916-12683- A	110	WT-042916-12683- B	82	Non-drinking water source - Not accessible to children			
2 KALORAMA RECREATION CENTER	5/26/2016	WS- 012692	Cooler	1	In hallway adjacent to main entrance Left High	WT-042916-12709- A	< 1	WT-042916-12709- B	< 1				
3 KALORAMA RECREATION CENTER	5/26/2016	WS- 012693	Cooler	1	In hallway adjacent to main entrance Right Low	WT-042916-12710- A	< 1	WT-042916-12710- B	< 1				
4 KALORAMA RECREATION CENTER	5/26/2016	WS- 012695	Fountain	Ground Floor	At basketball court on park side Left Low	WT-042916-12712- A	< 1	WT-042916-12712- B	< 1				
5 KALORAMA RECREATION CENTER	5/26/2016	WS- 012696	Fountain	Ground Floor	At basketball court at park side Right High	WT-042916-12713- A	< 1	WT-042916-12713- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.